

Computer 20




FIGURE 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5

```
graph TD; A([BEGIN]) --> B[RECEIVE HARDWARE ID FROM REMOTE COMPUTER]; B --> C[CREATE COMPUTER-EXECUTABLE INSTRUCTIONS FOR BLACK BOX BASED ON HARDWARE ID]; C --> D[PROVIDE BLACK BOX TO REMOTE COMPUTER]; D --> E([END]);
```

The flowchart illustrates a method for creating a black box for a remote computer. It begins with a terminal symbol labeled "BEGIN". An arrow points down to a process box labeled "RECEIVE HARDWARE ID FROM REMOTE COMPUTER", which is associated with reference numeral 601. Another arrow points down to a second process box labeled "CREATE COMPUTER-EXECUTABLE INSTRUCTIONS FOR BLACK BOX BASED ON HARDWARE ID", associated with reference numeral 602. A third arrow points down to a third process box labeled "PROVIDE BLACK BOX TO REMOTE COMPUTER", associated with reference numeral 603. Finally, an arrow points down to a terminal symbol labeled "END".

FIG. 6




FIG. 7




FIG. 8




FIG. 9